

VEHICLE INSPECTION REPORT

SJ15TWE

Vauxhall Vivaro 2900 1.6CDTI 115PS

Inspection

Serious Damage? No

Vehicle

VAT Plus VAT

V5 Buyer To Apply

Details

Reg. date 25/03/2015

Year 2015

Mileage 85,330 Miles Not Warranted

Fuel Type Diesel

Colour WHITE

VIN W0L3F7018FV625619

Body Style Panel Van MWB

MOT Due 15/01/2027

CAP Clean £3,150.00

CAP Average £2,525.00

CAP Below £1,775.00

Gearbox MANUAL

Gears 6

SIDE LOAD DOOR, ROOF RACK, E/MIRRORS.

Tyres

NSF

NSR

OSF


OSR

Spare

Features


- Radio/CD
- Front electric windows
- Central locking

Photos





Condition Check



Damage Photos



1: Seat Base Cover osf
Torn
Over 3mm



2: Sill os
Dented
Over 30mm



3: Bonnet
Dented
With Paint Damage

4: Door osf
Dented
With Paint Damage



5: Qtr Panel osr
Dented
Over 30mm

6: Tailgate
Dented
Over 30mm



7: Door nsr
Dented
With Paint Damage

8: Door nsf
Dented
Over 30mm



9: Wing nsf
Dented
With Paint Damage

Interior

Carpet Condition		Upholstery Condition	
Seat Condition	Average	Odour	Average
Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Turbo Boosting	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	OK
Windows	OK	Radio	OK
		Steering	OK